

4 LAYERS 0,70 +/- 0,1 LAB CODE:98

MATERIAL	THICKNESS
Basic copper	0,017
Prepreg 1080(2)	0,13 +/-0,01
Basic copper	0,035
FR4 0,356	0,35 +/-0,04
Basic copper	0,035
Prepreg 1080(2)	0,13 +/-0,01
Basic copper	0,017

4 LAYERS 1,0 +/- 0,1 LAB CODE:188

MATERIAL	THICKNESS
Basic copper	0,017
Prepreg 2113(2)	0,176 +/-0,02
Basic copper	0,035
FR4 0,508	0,5 +/-0,05
Basic copper	0,035
Prepreg 2113(2)	0,176 +/-0,02
Basic copper	0,017

4 LAYERS 1,15 +/- 0,1 LAB CODE: 5

MATERIAL	THICKNESS
Basic copper	0,017
Prepreg 7628(2)	0,346 +/-0,03
Basic copper	0,035
FR4 0,356	0,35 +/-0,04
Basic copper	0,035
Prepreg 7628(2)	0,346 +/-0,03
Basic copper	0,017

4 LAYERS 1,55 +/- 0,15 LAB CODE: 1

MATERIAL	THICKNESS
Basic copper	0,017
Prepreg 7628(2)	0,346 +/-0,03
Basic copper	0,035
FR4 0,737	0,73 +/-0,06
Basic copper	0,035
Prepreg 7628(2)	0,346 +/-0,03
Basic copper	0,017

4 LAYERS 1,8 +/- 0,15 LAB CODE: 107

MATERIAL	THICKNESS
Basic copper	0,017
Prepreg 7628(3)	0,519 +/-0,05
Basic copper	0,035
FR4 0,737	0,73 +/-0,06
Basic copper	0,035
Prepreg 7628(3)	0,519 +/-0,05
Basic copper	0,017

4 LAYERS 2,35 +/-0,2 LAB CODE: 9

MATERIAL	THICKNESS
Basic copper	0,017
Prepreg 7628(2)	0,346 +/-0,03
Basic copper	0,035
FR4 1,50	1,50 +/-0,1
Basic copper	0,035
Prepreg 7628(2)	0,346 +/-0,03
Basic copper	0,017

4 LAYERS 3,25 +/- 0,25 LAB CODE: 6

MATERIAL	THICKNESS
Basic copper	0,017
Prepreg 7628(2)	0,346 +/-0,03
Basic copper	0,035
FR4 2,42	2,42 +/-0,1
Basic copper	0,035
Prepreg 7628(2)	0,346 +/-0,03
Basic copper	0,017